


NORTHERN RAILWAY

Headquarters Office,
Baroda House,
New Delhi.

Dated: 2/1/2014

No.219-W/1/Maint/TP/2013-14



Sr.DEN/C,
Northern Railway,
DLI, MB, FZR, LKO & UMB.


Sub:- Lubrication of Rail Screws & Plate Screws.

It has been observed during inspection that lubrication of rail/plate screws is not being done resulting into excessive corrosion of screws. They also get jammed/loosened due to rusting.

For effective maintenance, CE circular (P.Way) No. 261 was issued for prevention of corrosion of plate and rails screw. It is being reiterated that this circular should be strictly followed. Record of locations of greasing of Plate/Rails screws should be maintained in separate register by each SSE/JE P.Way/Incharge (as per performa given in CE circular No. 261). This register should be kept in all inspections alongwith other registers. The circular is also uploaded in TMS and enclosed for ready reference.

This is for information and strict compliance please.

DA/As above.


(P.K.Sanghi)
Chief Track Engineer